

15 MAR '01

G.T.C.

USED WHEELBARROWS TO TAKE CONCRETE
INTO THE G.T.C. FILLED THE HOLES
I MADE LAST YEAR TAKING OUT
LOCKER PIERS. 4 HRS.

27 MAR '01

G.T.C.

TOOK THE DRILLER STATUE OUT TO THE
ROCK ON WHICH IT WILL BE MOUNTED.
MARKED WHERE TO DRILL 4 HOLES. TRIED
TO START THE EIMCO. NO LUCK. PUT
THE BATTERY ON CHARGE. MOVED A
LARGE PILE OF BRICKS AWAY FROM THE
NEW WORK SITE. MOVED TOOLS TO THE
NORTH SIDE OF THE G.T.C. SET UP
A JACK HAMMER AND STARTED CHIPPING
OUT A CONCRETE MACHINE BASE.
7 HRS.

28 MAR '01

PASSAIC PIT

GOT THE EIMCO STARTED BY WIRING
THE GLO-PLUGS DIRECTLY TO THE
BATTERY. HAD TO TAKE OFF THE
BLOWER AND CLEAN IT OUT. CLEANED
UP COAL THAT THE MOVIE CO. LEFT
NEAR THE RAINBOW TUNNEL.

7 HRS.

29 MAR '01

G.T.C.

FINISHED CLEANING UP COAL NEAR
THE RAINBOW TUNNEL, RENTED AN
ELECTRIC HAMMER DRILL, DRILLED
FOUR HOLES IN A BIG ROCK AND
MOUNTED THE DRILLER STATUE.

MOVED THE AIR COMPRESSOR CLOSER
TO THE NEW WORK SITE, CHIPPED
CONCRETE. HAND MUCKED CHIPPINGS
AND DUMPED A LOAD IN THE PIT.

7 HRS.

----- 25 -----

2 APR '01

G.T.C.

HAD TO CHARGED THE BATTERY TO
GET THE EIMCO STARTED. LAID OUT
A WATER HOSE FROM THE EDISON
TUNNEL. SET UP THE "53" AND
DRILLED HOLES. MOVED THE NEW
AIR COMPRESSOR TO THE WORK
SITE AND TRIED IT OUT. HAD TO
TIGHTEN A LEAKY DRAIN PLUG.
DRILLED HOLES AND WEDGED OUT
CONCRETE. DUMPED A LOAD IN THE
PIT. 7 HRS.

3 APR '01

G.T.C.

DRILLED HOLES AND WEDGED OUT CONCRETE. DUMPED A LOAD IN THE PIT. 7HRS

5 APR '01

G.T.C.

DRILLED HOLES AND WEDGED OUT CONCRETE. DISCOVERED THAT THE NEW COMPRESSOR BURNS A QUT. OF OIL A DAY. 7HRS.

6 APR '01

G.T.C.

WEDGED OUT CONCRETE. DUMPED A LOAD IN THE PIT. FUELED UP THE NEW COMPRESSOR, WHICH HAD RUN OUT OF GAS YESTERDAY, BUT IT WOULD NOT START. GOT RAINED OUT AFTER LUNCH. 4 HRS.

9 APR '01

G.T.C.

DRILLED HOLES AND WEDGED OUT CONCRETE. DUMPED A LOAD IN THE PIT. TOM HAUCK WORKED ON THE NEW COMPRESSOR SUNDAY. IT WORKS BETTER NOW. 7HRS.

10 APR '01

G.T.C.

DRILLED HOLES AND WEDGED OUT CONCRETE. DUMPED A LOAD IN THE PIT. THE DISCHARGE AIR TEMPERATURE GOT TOO HOT AND FRIED THE NEW COMPRESSOR.
7 HRS.

11 APR '01

G.T.C.

DRILLED HOLES AND WEDGED OUT CONCRETE. CHIPPED THE BIG BLOCK DOWN TO FINAL GRADE. FILLED THE EIMCO BUCKET, IT WOULD NOT START DESPITE CHARGING THE BATTERY FOR AN HOUR. 7 HRS.

--- 46 ---

16 APR '01

G.T.C.

THE STARTER ON THE EIMCO CRAPPED OUT. FOUND A SPARE BUT IT WOULD NOT FIT. COLORED THE INSIDE OF THE BELL HOUSING WITH RED CRAYON. THEN REMOVED METAL FROM THE STARTER WHERE IT WAS COLORED BY THE CRAYON. DUMPED TWO LOADS IN THE PIT. MOVED THE BAD COMPRESSOR OUT OF THE WAY. 7 HRS.

18 APR '01

G. T. C.

WORKED ON REMOVING REMAINS OF
OLD MILLING CIRCUIT IN THE OPEN
BAY ON THE NORTH SIDE OF THE G.T.C.
DUMPED THREE LOADS IN THE PIT.
USED THE EIMCO TO LOAD FOUR DRUMS
OF ROCK IN A SEMI. 7 HRS.

19 APR '01

G. T. C.

CLEANED THE OPEN BAY. DUMPED
FOUR LOADS IN THE PIT. A DUMP
TRUCK WAS TRYING TO DUMP FILL
IN THE PIT. THE TAIL GATE
FAILED TO OPEN AND THE TRUCK
FLIPPED BACK WITH THE CAB UP
IN THE AIR. 7 HRS.

20 APR '01

G. T. C.

WORKED IN THE OPEN BAY. DUMPED
FOUR LOADS IN THE PIT. PULLED
OUT LOTS OF WOOD AND STEEL.
THE YELLOW PINE 4X6'S STILL
HAD A STRONG PITCH ODOR. THERE
WERE THREE LAYERS OF STEEL.
WHEN THE FIRST LAYER OF 30 POUND
RAILS WORE OUT A NEW LAYER HAD
BEEN PUT IN ON TOP. 7 HRS.

23 APR '01

G.T.C.

USED ROB LEATHAM'S HILTI TO DRILL HOLES IN THE RAINBOW ROOM. PUT IN ANCHOR BOLTS TO HANG THE NEW TRIPLE-BRIGHT BLACK LITES. DID MORE DEMOLITION AT THE G.T.C. AND DUMPED TWO LOADS OF DEBRIS IN THE PIT. BOB BURNED OFF STEEL PINS THAT WERE EMBEDDED IN THE CONCRETE FLOOR. THE ACETYLENE HOSE LEAKED AND CAUGHT ON FIRE. 7 HRS.

24 APR '01

G.T.C.

FINISHED HANGING THE NEW U.V. LIGHTS IN THE RAINBOW ROOM. GOT MOST OF THE DEMOLITION DONE AT THE G.T.C. 7 HRS.

25 APR '01

G.T.C.

MMOVED THE SCRAP METAL FROM THE DEMOLITION TO A STORAGE AREA. CHIPPED DOWN SOME HIGH SPOTS IN THE FLOOR. SWEPT THE FLOOR AND HAND MUCKED. DUMPED A LOAD IN THE PIT. 7 HRS.

26 APR '01

G.T.C. & W.V.

FINISHED FINAL CLEAN-UP AT THE G.T.C.
DUMPED A LOAD IN THE PIT. PREPARED
A LEVEL PLACE NEAR THE WEST VEIN
FOR THE COMPRESSOR. MOVED THE
COMPRESSOR AND TOOLS TO THE NEW
WORK SITE. WORKED ON SETTING UP
AN OUTLET FOR DRILL WATER. HAD
TROUBLE WITH LEAKS AND RUSTY BOLTS.
7 HRS.

--- 56 HRS ---

30 APR '01

WEST VEIN

FINISHED THE OUTLET NEAR THE
RAINBOW TUNNEL FOR DRILL WATER.
SET UP THE "53" AND DRILLED 30
HOLES. WEDGED OUT THE FIRST
ROW. I AM EXPANDING THE HOLE
INTO THE WEST VEIN STOPE NEAR
THE RAINBOW TUNNEL. 7 HRS.

1 MAY '01

WEST VEIN

WEDGED OUT ORE. DUMPED TWO
LOADS ON THE PICKING DUMP.
POWER WASHED THE WALLS AND
BOULDERS IN THE RAINBOW ROOM.
THE EIMCO STARTER QUIT AGAIN.
7 HRS.

3 MAY '01

WEST VEIN

WEDGED OUT ORE. FILLED ONE
PAIL WITH GIVE-AWAY SAMPLES.
FIDDLED WITH THE DRILL WATER
SUPPLY TO GET RUST SCALE OUT
OF IT. DRILLED SIX HOLES. 7 HRS.

4 MAY '01

WEST VEIN

DRILLED HOLES AND WEDGED OUT ORE.
HAUCK SHOWED ME THE NEXT CHORE.
FIXING UP THE DRIFT TO THE
GRAVITY TRAM RAISE GRIZZLY.
7 HRS.

7 MAY '01

WEST VEIN

WEDGED OUT THE REST OF THE
HOLES IN THE WEST VEIN. CANT
MUCK OUT THE STOPE UNTIL WE
GET A STARTER FOR THE EIMCO.
SET UP THE "53" IN THE TUNNEL
TO THE GLORY HOLE GRIZZLY. HAD
TO SCROUNGE UP TWO AIR HOSES.
7 HRS.

8 MAY '01 GRIZZLY DRIFT

DRILLED PIN HOLES SO A GATE CAN BE INSTALLED AT THE ENTRANCE. BROKE BOULDERS ON THE GRIZZLY. A GRATE WILL BE PUT OVER IT FOR SAFETY. CLEANED UP BROKEN ROCK IN THE DRIFT WITH A WHEEL-BARROW. BOB USED HIS LOADER TO MOVE THE COMPRESSOR AND TOOLS TO THE SADDLE SOUTH OF THE PASSAIC PIT. 7 HRS.

9 MAY '01 GRIZZLY DRIFT

FINISHED CLEANING OUT THE DRIFT. USED A PICK AND BLOWPIPE TO CLEAN OFF THE NEXT WORK SITE. WILL BE WORKING ON AN AREA OF SCAPOLITE. MOVED THE DRILL TO THE SITE AND WORKED ON GETTING DRILL WATER THERE. 7 HRS.

10 MAY '01 SOUTH OF PASSAIC PIT

PUT NEW FITTINGS ON AN OLD WATER HOSE AND SET UP TO DRILL. DRILLED HOLES AND WEDGED OUT ROCK. THE OBJECTIVE IS FLUORESCENT SCAPOLITE. FOUND SOME MICROS IN VUGS. 7 HRS.

14 MAY '01 NORTH OF NOBLE PIT
DRILLED HOLES AND WEDGED OUT
SCAPOLITE. REPAIRED A WATER
HOSE BREAK. THE OIL BOTTLE HOSE
BLEW OFF THE GOOSE NECK, CAUSING
SOME EXCITEMENT. 7 HRS.

15 MAY '01 NORTH OF NOBLE PIT
DRILLED HOLES AND WEDGED OUT
SCAPOLITE. REPAIRED THE OIL BOTTLE
HOSE. BROKE THE 2' STEEL. REPLACED
IT WITH A 3' STEEL. THE END OF
THE 3' STEEL BROKE UP IN THE
CHUCK AND JAMMED THE DRILL. TOOK
THE DRILL APART. 7 HRS.

16 MAY '01 NORTH OF NOBLE PIT
HAD TO POUND THE STEEL OUT OF
THE CHUCK. PUT THE DRILL BACK
TOGETHER. DRILLED HOLES AND
WEDGED OUT SCAPOLITE. DRILLED
A LINE OF CLOSE HOLES AND
POPPED THE TOP OF THE ROCK OFF.
IT CONTAINS A CRYSTAL POCKET
WITH LARGE SCAPOLITES. WENT
BACK AFTER DARK TO SORT OUT
BETTER FLUORESCENCE. 7 HRS.

17 MAY '01

NORTH OF NOBLE PIT

HELPED BOB LOAD TWO BATCHES
OF ROCK. ONE IN HIS TRUCK AND
ONE IN HIS DOZER. THE SIDE BOLTS
ON THE DRILL WERE LOOSE. FIXED IT.
DRILLED HOLES IN A NEW PIECE OF
THE OUTCROP. WEDGED OUT ROCK.
GOT APATITE AND GALENA. 7 HRS.

18 MAY '01

NORTH OF NOBLE PIT

DRILLED TWO HOLES IN A LOOSE ROCK.
WEDGED OUT GALENA AND A PALE RED
FLUORESCING MINERAL. DRILLED OUT
A SMALL CRYSTAL POCKET. MOVED
TO THE AREA WHERE JEFFERSONITE
KLS ARE FOUND. DRILLED TWO HOLES
IN A CALCITE BOULDER. HAD TO ADD
A WATER HOSE AND REPAIR AN OLD
ONE. 7 HRS.

22 MAY '01

RAINBOW TUNNEL

SCALED LOOSE IN THE RAINBOW TUNNEL,
LANDMESSER TUNNEL AND EDISON TUNNEL.
FOUND ANOTHER EIMCO STARTER IN THE
CAP MAGAZINE. WORKED ON CLEANING IT.
RAINED OUT AFTER LUNCH. 4 HRS.

23 MAY '01 NORTH SIDE NOBLE PIT
SCALED LOOSE IN THE ADIT. DRILLED
HOLES AND WEDGED OUT ROCK IN THE
JEFFERSONITE AREA. RAIN IN THE LAST
TWO DAYS HAD TURNED THE AREA INTO
A MUDDY MESS. 7 HRS.

24 MAY '01 NORTH SIDE NOBLE PIT
DRILLED HOLES AND WEDGED OUT ROCK
IN THE JEFFERSONITE AREA. SAW
SOME FRANKLINITE XLS, BUT THEY
ARE NOT ATTRACTIVE. MOVED THE
DRILL TO THE WOLLASTONITE ZONE
AND DRILLED HOLES IN BOULDERS.
BROKE A 5' STEEL. STARTED
WEDGING BOULDERS. 7 HRS.

25 MAY '01 NORTH SIDE NOBLE PIT
DRILLED HOLES IN WOLLASTONITE BOULDERS
AND WEDGED THEM APART. 6 HRS.

--- 59 ---

31 MAY '01 WEST VEIN
INSTALLED A NEW STARTER IN THE
EIMCO. HAD TO FILE DOWN THE
NOSE TO GET IT IN. BEGAN TO
MUCK OUT THE OLD STOPE IN
THE WEST VEIN. A HYDRAULIC
HOSE BURST. WENT TO NEWTON
TO GET A NEW HOSE. USED A

CHAIN TO PULL A BIG CHUNK OF
ORE OUT OF THE STOPE. 7 HRS.

1 JUN '01 WEST VEIN
WORKED ON PULLING BIG SLABS
OUT OF THE WEST VEIN STOPE.
HAD TO HAND MUCK AROUND THEM
IN ORDER TO GET THE CHAIN HOOKED
UP. A BIG ONE IS STILL IN THE WAY.
THE EIMCO CAN'T BUDGE IT. 7 HRS.

4 JUN '01 NORTH SIDE NOBLE PIT
DRILLED HOLES AND WEDGED OUT
WOLLASTONITE. BOB MANAGED TO MOVE
THE BIG SLAB IN THE WEST VEIN
STOPE WITH HIS MACHINE. IT STILL
WOULD NOT COME OUT. I CAN DRILL
IT LATER. 7 HRS.

5 JUN '01 NORTH SIDE NOBLE PIT
DRILLED HOLES AND WEDGED OUT ROCK.
CLEANED OFF THE WOLLASTONITE OUT-
CROP. IT IS NOW READY TO DRILL.
USED THE BLOWPIPE TO EXCAVATE AN
AREA THAT MIGHT HAVE XLS. 7 HRS.

6 JUN '01

CHANGE HOUSE

DRILLED 3/8" HOLES NEAR THE FRONT AND BACK DOORS. INSTALLED ANCHOR BOLTS AND MOUNTED TWO STONE PLAQUES HONORING HARRY ZOBEL. HAD TO GO OUT TO A STORE TO GET A 3/8" MASONARY BIT. 7HRS

7 JUN '01

NORTH SIDE NOBLE PIT

DRILLED HOLES IN WOLLASTONITE. CLEANED UP THAT AREA. MADE A WATER HOSE REPAIR. DRILLED HOLES AND BROKE TWO BOULDERS. ONE CONTAINS XLS. 7HRS.

8 JUN '01

NORTH SIDE NOBLE PIT

FOUND A PATH THRU THE QUAGMIRE IN THE PASSAIC PIT AND GOT THE EIMCO TO THE WORK SITE. MUCKED DIRT AND ROCKS EXPOSING TWO PIECES OF OUT CROP. CLEANED THEM MORE WITH A BLOW PIPE.

7 HRS

- - - 49 - - -

11 JUN '01

NORTH SIDE NOBLE PIT

DRILLED AND BROKE UP BOULDERS. 7 HRS.

12 JUN '01

NORTH SIDE NOBLE PIT

DRILLED HOLES AND WEDGED OUT ROCK AT THE
MARGIN OF A CORRODED ZONE. MOVED BACK TO
THE SCAPOLITE AREA AND DRILLED SOME
HOLES. CLEANED OFF ANOTHER DRILL SITE.

7 HRS.

13 JUN '01

NORTH SIDE NOBLE PIT

MODIFIED THE LONG BLOWPIPE SO I
COULD BLOW OUT THE DOWN HOLES.

DRILLED A LINE OF 4' HOLES IN A
SCAPOLITE ZONE. DRILLED HOLES AND
WEDGED OUT ROCK AT THE FIRST
SCAPOLITE ZONE. 7 HRS.

14 JUN '01

NORTH SIDE NOBLE PIT

DRILLED HOLES AND WEDGED OUT ROCK
WHERE THE BIG SCAPOLITE POCKET CAME
FROM. GOT CRYSTAL POCKETS CONTAINING
BARITE AND CALCITE. 7 HRS.

15 JUN '01

NORTH SIDE NOBLE PIT

WASHED BROKEN ROCK FROM YESTERDAY.
DRILLED HOLES AND WEDGED OUT ROCK.
A TIRE BLEW OUT ON THE EIMCO WHILE
IT WAS PARKED. 4 HRS.

20 JUN '01 NORTH SIDE NOBLE PIT
CHANGED ~~A~~ A TIRE ON THE
EIMCO. DID SOME DIGGING AT
THE WORK SITE. MOVED COMPRESSOR
AND TOOLS TO THE WEST VEIN
STOPE. VERY HOT TODAY. 7 HRS.

21 JUN '01 WEST VEIN
THE SPARE TIRE I PUT ON YESTERDAY
HAS A SLOW LEAK. HAD TO AIR IT
UP TWICE. USED THE EIMCO TO
LOOSEN UP BIG CHUNKS OF GNEISS
AT THE GALENA-APATITE SITE.
GOT A SMALL SAMPLE WITH BARITE.
SET UP THE '53' AT THE WEST
VEIN STOPE. DRILLED HOLES IN
THE BIG SLAB (SEE 4 JUN) AND
WORKED ON WEDGING IT APART. 7 HRS.

22 JUN '01 WEST VEIN
PUT A NEW TIRE ON THE EIMCO.
DRILLED A ROW OF HOLES AND WEDGED
OUT ORE TO MAKE THE OPENING INTO
THE STOPE WIDER. MUCKED OUT THE
REST OF THE BIG SLAB. USED CHAINS
TO PULL BIG CHUNKS OUT OF THE
STOPE. 7 HRS.

-- - 53 - - -

26 JUN '01

WEST VEIN

PULLED BOULDERS OUT OF THE WEST
VEIN STOPE. HAD TO DRILL AND
BREAK A BIG ONE. 7 HRS.

27 JUN '01

WEST VEIN

PULLED MORE BOULDERS OUT OF
THE STOPES WITH CHAINS AND A
WIRE ROPE. CLEANED OFF THE
FOOT WALL UP TO THE AREA
WHERE BIG BOULDERS ARE JAMMED
IN. VERY HOT OUTSIDE BUT COOL IN
THE STOPES. 7 HRS.

28 JUN '01

WEST VEIN

CLEANED MORE MUCK OUT FROM
UNDER THE BIG BOULDERS. THEY
STILL WONT MOVE. GOT A GOOD
NOZZLE AND TRIED WATER ON
THEM BUT NO LUCK. 7 HRS.

29 JUN '01

WEST VEIN

USED ALL MY TRICKS AND GOT THE
NEST OF BIG BOULDERS TO COME
DOWN. 7 HRS.

3 JUL '01 WEST VEIN
HOOKED TWO TWENTY FOOT PIPES
TOGETHER AND POKED THE FILL
IN THE STOPE. AFTER ABOUT
TWO MINUTES A LARGE RUN OF
FILL CAME DOWN. BEGAN
MUCKING OUT THIS STUFF. THE
LARGEST PIECE HAD TO BE
DRILLED AND BROKEN INTO FOUR
PIECES BEFORE THE EIMCO
COULD MOVE IT. 7 HRS.

5 JUL '01 WEST VEIN
MUCKED OUT THE STUFF THAT
CAME DOWN IN THE LAST RUN.
CLEANED OFF THE FOOTWALL
AND POKED THE HANG-UP WITH
A 20' PIPE. GOT A BIG RUN
TO COME DOWN AND MUCKED
OUT SOME OF THAT. HAD TO
PUT DOWN A STEEL PLATE
WHERE THE EIMCO BUCKET
GOES IN THE STOPE. 7 HRS

--- 42 ---

9 JUL '01 WEST VEIN

DRAGGED ROCKS DOWN THE FOOT
WALL WITH A HOE AND MUCKED
THEM OUT WITH THE EIMCO.
STRUNG TOGETHER 40' OF PIPE
AND POKED AT HUNG UP ROCKS.
4 HRS.

10 JUL '01 WEST VEIN

DRAGGED MUCK DOWN WITH A HOE
AND PULLED CHUNKS DOWN WITH
CHAINS AND A CABLE. GETTING
SMALL STUFF OUT FROM UNDER
BIG HUNG-UP ROCKS WITH A 40'
PIPE. 7 HRS.

11 JUL '01 WEST VEIN

PULLED MORE MUCK DOWN THE
FOOTWALL WITH A HOE. PRODDED
THE BOTTOM OF THE HANGING MASS
WITH A 40' PIPE. WHILE EATING
LUNCH A LARGE RUN CAME DOWN.
BEGAN CLEANING THAT OUT. 7 HRS.

13 JUL '01

WEST VEIN

CLEANED MORE MUCK OFF THE FOOTWALL. THEN USED THE 40' PIPE TO GET A BIG RUN TO COME DOWN. IT HAD VERY LARGE PIECES IN IT. USED THE CABLE AND/OR CHAINS TO PULL CHUNKS OUT. WE NEEDED BOB'S LOADER TO PULL THE BIGGEST PIECE DOWN. IT IS TOO BIG TO COME OUT OF THE HOLE. I WILL HAVE TO DRILL AND BREAK IT. 7 HRS.

16 JUL '01


WEST VEIN

DRILLED AND BROKE THE BIG CHUNK. DRAGGED TWO PIECES OUT WITH THE EIMCO. THE REMAINING PIECE HAD TO BE DRILLED AND BROKEN AND THE EIMCO WAS JUST BARELY ABLE TO DRAG OUT THE BIGGEST REMNANT.

4 HRS. DRILLED TWO HOLES FOR ROCK BOLTS TO HANG A SLUSHER BLOCK.

17 JUL '01 WEST VEIN

RESET THE STEEL PLATE. MADE UP AND PUT IN A 3' BOLT TO HANG A SLUSHER BLOCK. CLEANED MUCK OFF THE FOOT WALL WITH A HOE. PULLED BIG PIECES DOWN WITH A CABLE AND/OR CHAINS. TRIED TWO BIG SLABS BUT THEY WONT MOVE. 7 HRS.



18 JUL '01 WEST VEIN

PULLED CHUNKS DOWN THE F/W WITH CABLE AND/OR CHAINS. CLEANED MUCK OUT OF THE DRIFT SO I COULD STAND IN IT AND WORK ON HUNG UP MUCK WITH A SCALING BAR. WHEN THE MUCK APPEARED TO BE READY TO GO I WENT DOWN TO GROUND LEVEL AND USED 50' OF PIPE TO POKE AT IT. A BIG

AVALANCH CAME DOWN. IT HAD
MANY BIG CHUNKS AND FILLED
THE BOTTOM PART OF THE STOPE.
SPENT THE REST OF THE DAY
WORKING ON THAT WITH THE
EIMCO. 7 HRS.

19 JUL '01

WEST VEIN

PULLED DOWN AND MUCKED OUT THE
REST OF THE BIG AVALANCH. DUG
OUT SOME TOOLS THAT GOT
BURIED IN THE DRIFT. TOOK TWO
BOULDERS OFF A TRUCK FROM
CANADA. LOADED A EAST VEIN
BOULDER AND A LARGE WOLLAST-
ONITE ON THE TRUCK. 7 HRS.

20 JUL '01

WEST VEIN

GOT MORE MUCK FROM HIGH UP
TO RUN DOWN. MUCKED OUT A
LOT OF STUFF. CLIMBED TO
THE TOP OF THE STOPE WITH A SCALING
BAR AND PRIED OUT SOME BIG
PIECES. A LOT MORE NEEDS TO BE
DONE THERE. 7 HRS.

- - - 57 HR - - -

23 JUL '01

WEST VEIN

PULLED DOWN AND MUCKED OUT MORE
ROCK. THE LAST PIECE WAS SO
BIG IT HAD TO BE DRILLED AND
BROKEN INTO 3 PARTS. BOB'S LOADER
WAS NEEDED TO PULL THEM OUT.
7 HRS.

24 JUL '01

WEST VEIN

PULLED DOWN AND MUCKED OUT
MORE ROCK. REPAIRED BLOWER
FAN BELT PULLEY ON THE EIMCO.
7 HRS.

25 JUL '01

WEST VEIN

PULLED DOWN A FEW PIECES WITH THE
CABLE AND GRAPPLING HOOK. POKED THE
ROCK ABOVE AND MANAGED TO GET
A MODERATE RUN OF MUCK. WANTED
TO WET DOWN THE DUSTY AREA WHERE
THE EIMCO OPERATES. IT TOOK AN
HOUR TO REPAIR THE WATER HOSE.
SUDDENLY A LARGE RUN OF MUCK
CAME DOWN WHICH CONTAINED SOME
TRULY HUGE PIECES. THE EIMCO
SPRUNG A HYDRAULIC LEAK. CANABAL-
IZED A PART OFF THE DISPLAY EIMCO
BUT IT LEAKS TOO. PULLED A FEW
BIG PIECES OUT, HAD TO DRILL AND
BREAK ONE. 7 HRS.

26 JUL '01

WEST VEIN

USED THE EXTENDED HOE TO CLEAN MUCK FROM UNDER A HUGE PIECE LAYING JUST ABOVE THE MUCKING POINT. IT CAME DOWN ALONG WITH ANOTHER BIG ONE. WORKED ON DRILLING HOLES AND BREAKING BOTH PIECES. CLIMBED TO THE TOP OF THE STOPE TO SEE WHERE THE BIG PIECES CAME FROM. IT LOOKS VERY DIFFERENT FROM THE LAST TIME I SAW IT. 7 HRS.

27 JUL '01

WEST VEIN

WORKED ON ~~THE~~ DRILLING AND BREAKING THE BIG PIECES, ONE WAS ROCK, THE OTHER NICE ORE. 7 HRS.

30 JUL '01

WEST VEIN

FINISHED BREAKING THE LAST BIG PIECE. NEEDED BOB'S LOADER TO DRAG OUT THE REMNANT. PULLED DOWN MUCK AND BOULDERS. THE LAST ONE WE GOT DOWN WILL HAVE TO BE DRILLED AND BROKEN.

7 HRS.

31 JUL '01

WEST VEIN

DRILLED AND BROKE THE BIG CHUNK LEFT OVER FROM YESTERDAY. PULLED MORE CHUNKS AND MUCK DOWN THE FOOTWALL. GOT A REALLY BIG PIECE TO MOVE 20' DOWN BUT IT IS STILL HUNG UP. BOB GOT A NEW HYDRAULIC HOSE TO REPLACE THE PIPE THAT LEAKS. SOON AFTER INSTALLING IT THE EIMCO LOST FORWARD DRIVE POWER. 6 HRS.

2 AUG '01

WEST VEIN

MUCKED OUT SOME ROCK UNTIL THE EIMCO QUIT WORKING. GOT THE POWER WASHER AND CLEANED AN ACCUMULATION OF GUNK OFF THE EIMCO HYDRAULIC SYSTEM SO I COULD TRY BLEEDING AIR OUT OF IT. IT DID NOT HELP. THE HYDRAULIC PUMP MAY BE WORN OUT. TRIED VARIOUS WAYS OF PULLING DOWN A BIG PIECE BUT EVEN BOB'S LOADER COULD NOT MOVE IT. 7 HRS.

3 AUG '01

WEST VEIN

MUCKED OUT THE LOOSE STUFF AT THE MUCKING POINT. THE EIMCO WILL WORK, POORLY, UNTIL IT GETS HOT. HAND MUCKED FINES OFF THE FOOTWALL TO UNDERMINE THE BIG PIECE. PULLED A SEMI-BIG PIECE OUT WITH BOB'S LOADER. 7 HRS.
--- 62 ---

6 AUG '01

WEST VEIN

DRILLED HOLES AND WEDGED OUT ORE ON THE NORTH SIDE OF THE HOLE INTO THE STOPE. BECAUSE THE EIMCO CAN'T MUCK ANY MORE WE HAVE TO USE BOB'S LOADER. 95° TODAY.
7 HRS.

7 AUG '01

WEST VEIN

DRILLED FOUR HOLES AND WEDGED OUT ORE. THE STOPE ENTRANCE IS NOW BIG ENOUGH FOR BOB'S LOADER. CONTINUED TO UNDERMINE THE BIG PIECE. 95° AGAIN.
7 HRS.

8 AUG '01

WEST VEIN

REMOVED ROCKS FROM AROUND THE
BIG PIECE. NO LUCK. HAND MUCKED
FINES OUT FROM UNDER IT
AND IT FINALLY SLID DOWN.
7 HRS. 95° TODAY

9 AUG '01

WEST VEIN

DRILLED MANY HOLES IN THE BIG
PIECE AND BROKE IT INTO ABOUT
SIX PIECES. BOB'S LOADER WAS
JUST BARELY ABLE TO DRAG OUT
THE BIGGEST ONE. PULLED ROCKS
DOWN THE F/W AND MUCKED
THEM OUT. 7 HRS. 98°

10 AUG '01

WEST VEIN

HAND MUCKED AND PULLED DOWN
SOME BIG PIECES WITH CABLE
AND CHAINS. THIS MADE ROOM FOR
THE NEXT RUN OF MUCK, USED
A LONG SCALING BAR TO GET
A GOOD RUN OF MUCK INCLUDING
SOME BIG PIECES, ~~>~~ 6.5 HRS.

13 AUG '01

WEST VEIN

HAND MUCKED SMALL STUFF
AND PULLED DOWN BIG PIECES
WITH CABLE AND/OR CHAINS.
BOB'S LOADER WAS STRAINING
ON SOME OF THEM. 7 HRS.

14 AUG '01

WEST VEIN

PULLED DOWN PIECES WITH CABLE
AND/OR CHAINS. MUCKED THEM OUT
UNTIL THE EIMCO GOT TIRED. CLIMBED
TO THE TOP OF THE STOPE AND PRIED
OUT MUCK WITH A LONG SCALING BAR.
BOB MUCKED OUT THE RESULT WITH
HIS LOADER. 7 HRS.

15 AUG '01

WEST VEIN

DID THE SAME AS YESTERDAY
EXCEPT THAT THIS TIME I CLIMBED
TO THE TOP BY WALKING UP THRU
THE STOPE. 7 HRS.

16 AUG '01

WEST VEIN

PULLED DOWN BIG PIECES AND HAND
MUCKED, SPENT THE AFTERNOON
AT THE TOP OF THE STOPE.
7 HRS.

- - - 62.5 - - -

20 AUG '01

WEST VEIN

HAND MUCKED AND PULLED DOWN BIG
PIECES WITH CHAINS AND/OR CABLE.
7 HRS.

MISSED 4 DAYS - STRAINED RIB CAGE

27 AUG '01

EAST VEIN

MOVED COMPRESSOR AND TOOLS
TO A NEW LOCATION ON THE
EAST VEIN. WE ARE SHUTTING
DOWN THE WEST VEIN STOPE
DUE TO A CLOSE CALL WHEN
BOB WAS NEARLY MASHED BY
A PIECE WHICH FELL OFF THE
HANGING WALL. 7 HRS.

28 AUG '01

EAST VEIN

DRILLED HOLES AND WEDGED
OUT FOOTWALL ROCK. 7 HRS.

29 AUG '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT
ORE AND ROCK. 7 HRS.

31 AUG '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE
AND ROCK. 5 HRS.

--- 33 HRS ---

4 SEP '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. 7 HRS.

5 SEP '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. IT IS NICE RED & GREEN. SEPARATED OUT 4 BIG PIECES THAT BOB WANTS FOR A CLIENT. 7 HRS.

7 SEP '01

EAST VEIN

CLEANED OFF THE OUTCROP WITH A SHOVEL. DRILLED HOLES AND WEDGED OUT ORE. 7 HRS.

10 SEP '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. THE SHANK ON THE STEEL BROKE UP IN THE DRILL. HAD TO TAKE THE CHUCK OUT AND POUND THE STEEL OUT OF IT. 7 HRS.

11 SEP '01

EAST VEIN

REASSEMBLED THE "53" AND PREPARED A NEW 3' STEEL. DRILLED HOLES AND WEDGED OUT ORE. THE PASSAIC PIT IS LIKE A MEGAPHONE, MAGNIFYING SOUND. HEARD A STRANGE NOISE